

CALIFORNIA DEPARTMENT OF HEALTH SERVICES

WORKER

CRUSHED!



CAUGHT BETWEEN DIE PLATES WHILE REPAIRING INJECTION MOLDING MACHINE

A 47-year-old mechanic, Frank M.*, died when he stood between the die plates of an injection molding machine to perform repairs. A supervisor closed a safety door which allowed the machine to run before Frank had a chance to get out.

WHAT WENT WRONG?	WHAT SHOULD BE DONE?
The machine was not shut off before the repair.	Always lockout and tagout machines before repair.
The die plates were able to move.	Use blocks or "dogs" to keep machine parts from moving.
Frank was standing between the die plates.	Use long-handled tools to stay out of pinch points.
The supervisor shut the safety door with Frank inside.	Make sure safety doors stay open during repairs.

For complete fatality reports of these (98CA001 and 01CA007) or other cases, and information on the **Fatality Assessment and Control Evaluation (FACE) Program**, contact:


California Department of Health Services Occupational Health Branch, FACE Program 1515 Clay Street, Suite 1901, Oakland, CA 94612 or visit our website at **www.dhs.ca.gov/ohb/ohsep/face.**

To obtain a copy of this document in an alternate format, please contact: OHB at (510) 622-4300

or CA Relay Service at (800) 735-2929

Please allow at least ten working days to coordinate alternate format services.









Gray Davis, Governor State of California Grantland Johnson, Secretary Health and Human Services Agency Diana M. Bontá, R.N., Dr.P.H. Director, Department of Health Services

AUGUST 2003

PLEASE POST

FACE stands for "Fatality Assessment and Control Evaluation." The purpose of the FACE Program is to find problems that may cause work-related deaths so that employers and employees can help prevent them.

FACE is a public health program run by the California Department of Health Services, Occupational Health Branch and funded by the National Institute for Occupational Safety and Health.

California Department of Health Services

Occupational Health Branch, FACE Program

1515 Clay Street, Suite 1901

Oakland, CA 94612